
Sh t 1 of 9

FIG.1




 Robert C. Colwell, Reg. No. 27.431

(650) 326-2400

Applicant: Michiobu Mizumura, et al. T lat Panel Display Unit and Method of Repairing..

Atty Docket No. 16869P-031900 Sheet 2 of 9

FIG.2



12 : Glass pipette13 : Insulating film material13' : Insulating film material coating range

N

Applicant: Michiobu Mizumura, et al. Flat Panel Display Unit and Method of Repairing

Atty Docket N . 16869P-031900

Sheet 3 f 9

FIG.3





FIG.4




Applicant: Michiobu Mizumura, et al.

Flat Panel Display Unit and Method of Repairing.


Atty D ck t No. 16869P-031900

Sheet 4 of 9

FIG.5



n.




Cross section along B-B'


Applicant: Michiobu Mizumura, et al. at Panel Display Unit and Method of Repairing... Atty Docket N . 16869P-031900

She t 5 of 9

FIG.6



TU



Cross section along C-C'

17 : Foreign object18 : Insulating film material


The party of the species of the spec

ħJ

Applicant: Michiobu Mizumura, et al. lat Panel Display Unit and Method of Repairing. Atty Docket No. 16869P-031900

Sheet 6 of 9

FIG.7




19: Foreign object

Applicant: Michiobu Mizumura, et al. at Panel Display Unit and Method of Repairing..

Atty Dock t No. 16869P-031900

She t 7 of 9

FIG.8



1 : Glass substrate

2 : Scan line

3 : Signal line


4 : Pixel

6: TFT structure

7: Shorting defect portion

gi D1 Œ į. L. ļai.

FIG.9



 Robert C. Colwell, Reg. No. 27,431

(650) 326-2400


Applicant: Michiobu Mizumura, et al.

Ti lat Panel Display Unit and Method of Repairing...

Atty Docket No. 16869P-031900

Sheet 9 of 9

FIG.10



8: Inter-layer insulating film

9: Laser

10 : Dispersed metal11, 11' : Portion severed by laser

Company of the state of the sta n ŤIJ